

## PEES Power Systems

# Kampala electricity safety

**Nominal Capacity**

**280Ah**

**Nominal Energy**

**50kW/100kWh**

**IP Grade**

**IP54**



## Overview

---

Police warn on electrical safety after fatal electrocution in the city. Kampala, Uganda: A young couple in Katwe Nkere Zone, Makindye Division, has died in a fatal electrocution incident linked to an illegal electricity connection, Kampala Metropolitan Police confirmed Thursday. The accident occurred on. Let those sabotaging our electricity infrastructure be warned—jail awaits you, and the consequences will be severe Police has warned individuals involved in the sabotage of Uganda's electricity infrastructure, saying those found culpable will face severe consequences. We reviewed reports by the main power distributor (UMEME/UEDCL), interviewed. A five-year-old girl has died after being electrocuted by a live electric wire in Kakunguru Zone, Kibuli, in Kampala's Makindye Division, police have said. The deceased have been identified as Ssefuma Charles and Namayube Tina, who were reportedly electrocuted due to an.

## Kampala electricity safety

---



### Why Kampala Keeps Going Dark: What's Really Behind the Outages

In order to ground ourselves deeper into the problem of energy resilience in Uganda, we decided to do some exploratory research into the actual root cause of power outages in urban areas ...

---

### Five-Year-Old Girl Electrocuted by Live Power Line in Kampala

Fatal electrocution incidents linked to faulty or exposed power lines have remained a recurring safety concern in parts of Kampala, especially in densely populated neighbourhoods where ...



✓ TELECOM CABINET

✓ BRAND NEW ORIGINAL

✓ HIGH-EFFICIENCY



### Kampala Electrical Service

Ensuring the safety of your home's electrical system is paramount, and Kampala Electrical Services offers expert guidance. Our comprehensive tips for maintaining electrical safety provide homeowners ...

## Teen worker electrocuted at construction site in Kampala

Police warn on electrical safety after fatal electrocution in the city. Police have launched an investigation into a fatal electrocution incident that left a 19-year-old man dead and another



## electrical safety Kampala Archives

UGANDA, Kampala , Real Muloodi News , A quiet afternoon in Bruno Zone, Lower Konge in Kampala's Makindye Division turned tragic when...

## Police Warn Electricity Vandals: Jail Awaits You

Let those sabotaging our electricity infrastructure be warned--jail awaits you, and the consequences will be severe. Police has warned individuals involved in the sabotage of Uganda's ...



## BREAKING! Couple Electrocuted in Illegal Electricity Connection

Onyango said that police strongly suspect the electrocution was caused by

an illegal electricity connection. He appealed to the public to refrain from making such hazardous connections, ...



## "Then electricity theft would end, nobody loves stealing": Community

This research sought to understand and describe the electrical realities of people living in informal settlements in Kampala, Uganda, and to document the difficulties they faced in accessing ...



## Illegal Power use, one killed in Kampala-Uganda

UEDCL sternly warned the public that unauthorized access to the electricity network, often for illegal power hookups, is extremely hazardous and frequently leads to fatal accidents.

## Katwe couple electrocuted in illegal power connection tragedy

The incident has prompted fresh calls for vigilance and public awareness, with the police confirming that a community-based safety campaign is being launched to address rising cases of ...



---

## Contact Us

---

For catalog requests, pricing, or partnerships, please visit:  
<https://www.peregrine-energy.co.za>

